

WYNN DRESSER

Assembly instructions:

PART LISTS

NO.	DESCRIPTION	IMAGE	Q'TY
P1	DRESSER TOP		2PCS
P2	LEGS		4PCS
Р3	CENTER LEG	Û	1PC

HARDWARE LISTS

NO.	DESCRIPTION	IMAGE	Q'TY
H1	BOLT 5/16" X20 mm		10PCS
H2	METAL PLATE	6/9	4PCS
НЗ	ALLEN KEY		1PC
H4	TIPPING RESTRAINT	9	1SET
Н5	PHILIP SCREW		NOT PROVIDE

NOTE: PO# is located underneath/ inside of each item. Please be prepared to provide this # should any claim be necessary.

CAUTION: Item is heavy assembly should be performed by two people.

Estimate assenbly time:6.5 minutes

